

Part-2

(To be filled by S.D.E of P.W.D. B&R Department)

Name of School **Baba Isher Singh Baba Kundan Singh (N) Public School Jhoraran**
I have visited the above mentioned school on 08/08/2025 and have visually inspected it from all angles of safety and I found it fit for normal use as school building.

In case any addition/alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may be obtained after the completion of the work from the undersigned.

In case the building is affected by flood or if there is settlement of walls/foundations or caves of roof etc . immediately inspection of the undersigned be arranged or check the stability and safety of the building.

This building can be safely occupied for normal use up to Date 31-03-2026 (Indicate year upto which it can be used). (for year 2025-26)




Sub Divisional Engineer
Construction Sub Division
PWD (B&R) Jagraon at Ludhiana

ਪਿੱਠ ਅੰਕਣ ਨੰ: 327-328

ਮਿਤੀ: 14/8/2025

1. ਉਪਰੋਕਤ ਸਕੂਲ ਦਾ ਇਸ ਦਫ਼ਤਰ ਦੇ ਜੂਨੀਅਰ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਨਿਰੀਖਣ ਕੀਤਾ ਗਿਆ ਅਤੇ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਸੇਫ਼ ਪਾਈ ਗਈ। ਇਸ ਲਈ ਸਾਲ 2025-26 ਦੌਰਾਨ ਮਿਤੀ 31.03.2026 ਤੱਕ ਦਾ ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫ਼ਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।
2. ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ: 1, ਲੋ:ਨਿ:ਵਿ:, ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਲੁਧਿਆਣਾ ਨੂੰ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।


Sub Divisional Engineer
Construction Sub Division
PWD (B&R) Jagraon at Ludhiana